

ANALOG CLAMP METER 7110

APPLICATION: This is an Analog Clamp Meter. This instrument can be used to measure, AC/DC Voltage, AC Current, Resistance, Temperature. It is an ideal tool for the Electricians, Engineers, Factories, Industries, Laboratories, Students, Household.

FEATURES:

- Display: Analog
- CAT II 600V
- Operating & Storage Temperature & Humidity: -5°C To 40°C, <75%RH
- Clamp Jaw Opening Size: 40mm
- Power supply: 1.5 Volt Batteries (AA size)
- Dimension: 198×80×36mm
- Weight: 320 gms Including Battery
- Accessories: Instruction Manual, Batteries, Test lead, Carrying Pouch.

SPECIFICATION:

Basic Function	Range	Best Accuracy
AC Current	6A/15A/60A/150A/300A	±3%
AC Voltage	150V/300V/600V	±3%
DC Voltage	60V	±3%
Resistance	2kΩ	±4%
Temperature	150°C	±5°C(0°C-100°C), ±10°C(Beyond the range)

